

### Fletcher Trace Parkway Headwall Replacement

Two storm sewer outfall structures on Fletcher Trace Parkway were deteriorating and structurally unstable. The structures support three to four storm sewer pipes each which convey a large amount of stormwater from upstream neighborhoods to Fletcher Creek. The headwall located on Fletcher Trace Parkway and Eton Cove was replaced in 2010. The headwall located on Fletcher Trace Parkway and Slezenger Drive was replaced in 2011.

Fletcher Creek headwalls before repairs:



Fletcher Creek headwalls after repairs:

